
Contents

| | |
|---|------------|
| Preface | vii |
| CHAPTER 1 | |
| Inspection Methods—Overview and Comparison | 1 |
| Visual Inspection | 1 |
| Coordinate Measuring Machines | 2 |
| Machine Vision | 3 |
| Hardness Testing | 5 |
| Tensile Testing | 7 |
| Chemical Analysis | 9 |
| Metallography | 9 |
| Nondestructive Testing | 11 |
| CHAPTER 2 | |
| Visual Inspection | 21 |
| Visual Inspection Procedure | 21 |
| Visual Inspection Tools | 27 |
| CHAPTER 3 | |
| Coordinate Measuring Machines | 49 |
| CMM Operating Principles | 50 |
| Types of CMMs | 54 |
| CHAPTER 4 | |
| Machine Vision | 63 |
| Machine Vision Process | 66 |
| Machine Vision Applications | 82 |

| | |
|--|------------|
| CHAPTER 5 | |
| Hardness Testing | 85 |
| Brinell Hardness Testing | 85 |
| Rockwell Hardness Testing | 91 |
| Vickers Hardness Testing (ASTM E384). | 100 |
| Scleroscope Hardness Testing | 102 |
| Microhardness Testing | 106 |
| | |
| CHAPTER 6 | |
| Tensile Testing | 117 |
| Stress-Strain Behavior | 117 |
| Properties from Test Results | 118 |
| Testing Machines | 124 |
| General Procedures | 129 |
| | |
| CHAPTER 7 | |
| Chemical Composition | 139 |
| X-Ray Fluorescence Spectroscopy (XRF). | 139 |
| Optical Emission Spectroscopy (OES) | 146 |
| Combustion and Inert Gas Fusion Analysis. | 150 |
| Surface Analysis. | 152 |
| Scanning Auger Microprobe (SAM) | 152 |
| Related Surface Analysis Techniques | 158 |
| | |
| CHAPTER 8 | |
| Metallography | 161 |
| Sectioning | 162 |
| Mounting of Specimens | 162 |
| Grinding | 164 |
| Polishing | 166 |
| Etching | 170 |
| Microscopic Examination | 171 |
| Microphotography | 180 |
| Grain Size. | 181 |
| | |
| CHAPTER 9 | |
| Liquid Penetrant, Magnetic Particle, and Eddy-Current | |
| Inspection | 183 |
| Liquid Penetrant Inspection | 183 |
| Magnetic Particle Inspection | 197 |
| Eddy Current Inspection | 215 |

CHAPTER 10**Radiographic Inspection 233**

| | |
|---|-----|
| Uses of Radiography | 234 |
| Principles of Radiography | 236 |
| Sources of Radiation | 237 |
| X-Ray Tubes | 239 |
| Attenuation of Electromagnetic Radiation. | 243 |
| Principles of Shadow Formation | 246 |
| Image Conversion | 248 |
| Characteristics of X-Ray Film | 254 |
| Exposure Factors | 257 |
| Neutron Radiography. | 262 |

CHAPTER 11**Ultrasonic Inspection 267**

| | |
|---|-----|
| Ultrasonic Flaw Detectors | 268 |
| Ultrasonic Transducers and Search Units | 269 |
| Couplants | 271 |
| Basic Inspection Methods | 272 |
| Pulse Echo Method | 273 |
| Transmission Methods | 280 |
| General Characteristics of Ultrasonic Waves. | 282 |
| Factors Influencing Ultrasonic Inspection | 285 |
| Advantages, Disadvantages, and Applications | 291 |

CHAPTER 12**Inspection of Castings. 293**

| | |
|---|-----|
| Inspection Categories. | 293 |
| Casting Defects | 294 |
| Common Inspection Procedures | 299 |
| Computer-Aided Dimensional Inspection | 302 |
| Liquid Penetrant Inspection | 308 |
| Magnetic Particle Inspection | 309 |
| Eddy Current Inspection | 310 |
| Radiographic Inspection | 310 |
| Ultrasonic Inspection | 314 |
| Leak Testing. | 318 |

CHAPTER 13**Inspection of Steel Bar and Wire. 321**

| | |
|---|-----|
| Types of Flaws Encountered | 321 |
| Methods Used for Inspection of Steel Bars | 324 |

| | |
|--|------------|
| CHAPTER 14 | |
| Inspection of Tubular Products | 345 |
| Selection of Inspection Method | 346 |
| Inspection of Resistance Welded Steel Tubing | 347 |
| Seamless Steel Tubular Products | 356 |
| Nonferrous Tubing | 362 |
| CHAPTER 15 | |
| Inspection of Forgings | 365 |
| Flaws Originating in the Ingot | 365 |
| Flaws Caused by the Forging Operation | 370 |
| Selection of Inspection Method | 371 |
| Visual Inspection | 383 |
| Magnetic Particle Inspection | 383 |
| Liquid Penetrant Inspection | 387 |
| Ultrasonic Inspection | 389 |
| Radiographic Inspection | 391 |
| CHAPTER 16 | |
| Inspection of Powder Metallurgy Parts | 393 |
| Dimensional Evaluation | 393 |
| Density Measurement | 394 |
| Apparent Hardness and Microhardness | 396 |
| Mechanical Testing/Tensile Testing | 397 |
| Powder Metallurgy Part Defects | 398 |
| Flaw Detection | 400 |
| CHAPTER 17 | |
| Inspection of Weldments and Brazed Assemblies | 411 |
| Weldments | 411 |
| Methods of Nondestructive Inspection | 421 |
| Brazed Assemblies | 437 |
| Methods of Inspection | 442 |
| Index | 447 |