

---

# CONTENTS

---

	<b>Preface</b>	<b>xiii</b>
<b>Chapter 1</b>	<b>Macrostructure</b>	<b>1</b>
1-1	Introduction	1
1-2	Visualization and Evaluation of Macrostructure by Etching	2
1-2.1	Macroetching with Acid Solutions	3
1-2.2	Copper-Containing Macroetchants for Primary Structure	5
1-2.3	Macroetchants for Revealing Strain Patterns	7
1-2.4	Macroetch Specifications	9
1-2.5	Classification of Macroetch Features	11
1-3	Applications of Macroetching	13
1-3.1	Solidification Structures	13
1-3.2	Billet and Bloom Macrostructures	15
1-3.3	Continuously Cast Steel Macrostructures	19
1-3.4	Consumable Electrode Remelted Steel Macrostructures	20
1-3.5	Dendrite Arm Spacing	21
1-3.6	Forging Flow Lines	27
1-3.7	Grain or Cell Size	30
1-3.8	Alloy Segregation	32
1-3.9	Carbide Segregation	33
1-3.10	Weldments	33
1-3.11	Strain Patterns	36
1-3.12	Failure Analysis	36
1-3.13	Response to Heat Treatment	39
1-3.14	Flame Cutting	39
1-4	Macrostructure Revealed by Machining	41
1-5	The Fracture Test	41
1-5.1	Composition	42
1-5.2	Inclusion Stringers	42

vi CONTENTS

1-5.3	Degree of Graphitization	43
1-5.4	Grain Size	44
1-5.5	Depth of Hardening	44
1-5.6	Detection of Overheating	45
1-5.7	Evaluation of Quality	45
1-6	Special Print Methods	47
1-6.1	Contact Printing	47
1-6.2	Sulfur Printing	47
1-6.3	Oxide Printing	52
1-6.4	Phosphorus Printing	52
1-6.5	Lead Printing and Exudation Test	53
1-6.6	Miscellaneous Print Methods	56
1-7	Summary	57
<b>Chapter 2</b>	<b>Specimen Preparation for Light Microscopy</b>	<b>60</b>
2-1	Introduction	60
2-2	Sample Selection	60
2-3	Sectioning	62
2-3.1	Fracturing	62
2-3.2	Shearing	62
2-3.3	Sawing	63
2-3.4	Abrasive Cutting	63
2-3.5	Microtomy	69
2-3.6	Wire Saws	69
2-3.7	Electric Discharge Machining	70
2-3.8	Micromilling	70
2-3.9	Summary	70
2-4	Mounting	71
2-4.1	Cleaning	72
2-4.2	Adhesive Mounting	73
2-4.3	Clamps	73
2-4.4	Plastic Mounting Materials	75
	<i>Compression Mounting / Castable Mounts</i>	
2-4.5	Vacuum Impregnation	85
2-4.6	Taper Mounting	86
2-4.7	Edge Preservation	86
2-4.8	Conductive Mounts	91
2-4.9	Special Mounting Techniques	92
2-4.10	Mount Marking and Storage	92
2-4.11	Summary	93
2-5	Grinding	93
2-5.1	Grinding Media	95
2-5.2	Equipment	98
2-5.3	Lapping	100
2-6	Polishing	101
2-6.1	Equipment	103
2-6.2	Polishing Cloths	104
2-6.3	Polishing Abrasives	105
2-7	Grinding and Polishing Theory	112

2-8	Electromechanical Polishing	115
2-9	Attack Polishing	116
2-10	Chemical Polishing	117
2-11	Electropolishing	119
	2-11.1 Advantages	120
	2-11.2 Disadvantages	120
	2-11.3 Equipment	121
	2-11.4 Theory	121
	2-11.5 Factors Influencing Electropolishing	124
	2-11.6 Comparison of Mechanically and Electrolytically Polished Surfaces	125
2-12	Specific Polishing Recommendations	127
	2-12.1 Universal Methods	127
	2-12.2 Common Problems	127
	<i>Coatings / Graphite and Inclusion Retention</i>	
	2-12.3 Metals	132
	<i>Aluminum / Antimony and Bismuth / Beryllium / Cadmium, Lead, Tin, and Zinc / Chromium, Molybdenum, and Tungsten / Cobalt, Manganese, Nickel, and Iron / Copper / Germanium and Silicon / Indium and Thallium / Magnesium / Niobium, Tantalum, and Vanadium / Precious Metals / Radioactive Metals / Rare Earth Metals / Selenium and Tellurium / Sodium / Titanium / Zirconium and Hafnium</i>	
	2-12.4 Borides and Carbides	141
	2-12.5 Carbonaceous Materials	142
	2-12.6 Ceramics	143
	2-12.7 Composites	144
	2-12.8 Minerals	144
	2-12.9 Polymers	146
2-13	Safety	148
	2-13.1 Solvents	151
	2-13.2 Acids	153
	2-13.3 Other Chemicals	157
	2-13.4 Summary	158
2-14	Summary	159
<b>Chapter 3</b>	<b>Microstructure</b>	<b>165</b>
3-1	Introduction	165
3-2	Etching	166
	3-2.1 Etching Theory	166
	3-2.2 Etching Technique	171
	3-2.3 Etching Problems	172
	3-2.4 Tint Etching	174
	3-2.5 Electrolytic Etching	177
	3-2.6 Anodizing	178
	3-2.7 Potentiostatic Etching	178
	3-2.8 Polarized-Light Etchants	180
3-3	Heat Tinting	182

**viii** CONTENTS

3-4	Thermal Etching	185
3-5	Gas Contrasting	186
3-6	Vapor-Deposited Interference Films	187
3-7	Magnetic “Etching”	190
3-8	Ion-Bombardment Etching	191
3-9	Dislocation Etch Pitting	192
3-10	Corrosion Tests	194
3-11	Specific Etching Recommendations	195
3-11.1	Metals	195
	<i>Aluminum and Alloys / Antimony and Bismuth / Beryllium / Cadmium, Lead, Tin, and Zinc / Chromium, Molybdenum, and Tungsten / Cobalt and Manganese / Copper and Alloys / Germanium and Silicon / Indium and Thallium / Iron and Steels / Magnesium and Alloys / Nickel and Alloys / Niobium, Tantalum, and Vanadium / Precious Metals / Radioactive Metals / Rare Earth Metals / Selenium and Tellurium / Titanium and Alloys / Zirconium and Hafnium</i>	
3-11.2	Borides, Carbides, Nitrides, and Oxides	254
3-11.3	Polymers	257
3-11.4	Minerals	257
3-12	Summary	258
<b>Chapter 4</b>	<b>Light Microscopy</b>	<b>267</b>
4-1	Introduction	267
4-2	Basic Concepts in Light Optical Theory	268
4-3	The Light Microscope	270
4-3.1	Illumination	271
	<i>Low-Voltage Tungsten Filament Lamp / Carbon Arc / Xenon Arc / Quartz-Iodine Lamp / Zirconium Arc Lamp / Mercury Vapor Lamp</i>	
4-3.2	Condenser System	274
4-3.3	Light Filters	274
4-3.4	Objective Lens	275
4-3.5	Eyepieces	278
4-3.6	Stage	280
4-3.7	Control of Microscope Variables	281
4-3.8	Lens Defects	282
4-3.9	Resolution and Depth of Field	282
4-4	Examination Modes in Light Microscopy	292
4-4.1	Methods of Examination	292
	<i>Bright-Field Illumination / Oblique Illumination / Dark-field Illumination / Polarized Light / Phase-Contrast Illumination / Interference Techniques / Ultraviolet Microscopy / Light-Section Microscopy / Fluorescence Microscopy / Infrared Microscopy</i>	
4-5	Light Phenomena	309
4-6	Photomicrography	312
4-6.1	Obtaining Good Photomicrographs	313

4-6.2	Black-and-White Photography	314
4-6.3	Color Photography	316
4-6.4	Film Handling	317
4-7	Photomacrography	318
4-8	Auxiliary Techniques	322
4-8.1	Microhardness	322
4-8.2	Hot-Stage Microscopy	322
4-8.3	Special States for <i>In Situ</i> Experiments	323
4-8.4	Hot-Cell Microscopy	326
4-8.5	Field Microscopy	327
4-8.6	Comparison Microscopes	328
4-8.7	Television Monitors	328
4-8.8	Clean-Room Microscopy	329
4-9	Summary	329
<b>Chapter 5</b>	<b>Hardness</b>	<b>334</b>
5-1	Introduction	334
5-2	Indentation Hardness	335
5-2.1	Relationship to Stress-Strain Curve	335
5-2.2	Effects of Time, Velocity, and Size	337
5-2.3	Effects of Lubrication and Adhesion	338
5-2.4	Indentation Size and Shape Changes	338
5-2.5	Surface Roughness	339
5-3	Static Hardness Tests	339
5-3.1	Brinell Hardness	339
5-3.2	Meyer Hardness	346
5-3.3	Vickers Hardness	350
5-3.4	Rockwell Hardness	355
5-3.5	Other Static Hardness Tests	366
	<i>Ludwik Conical Indentation Test / Mutual Indentation Tests / Mallock Cone Test / Scratch Hardness / Hardness Tests for Nonmetallic Materials</i>	
5-4	Dynamic Hardness Tests	369
5-4.1	Shore Scleroscope	370
5-4.2	Pendulum Hardness	371
5-4.3	Cloudburst Test	371
5-4.4	Equotip Hardness	371
5-5	Nondestructive Hardness Tests	372
5-6	Microindentation Hardness	373
5-7	Hardness Conversions	382
5-8	Applications	383
5-8.1	Anisotropy	383
5-8.2	Indentation Fracture	385
5-8.3	Machinability	389
5-8.4	Phase Identification	391
5-8.5	Prediction of Other Properties	391
5-8.6	Quality Control	393
5-8.7	Residual Stress	396
5-8.8	Temperature Effects	396

**x CONTENTS**

5-8.9	Wear	398
5-8.10	Miscellaneous Applications	403
5-9	Summary	404
<b>Chapter 6</b>	<b>Quantitative Microscopy</b>	<b>410</b>
6-1	Introduction	410
6-2	Basic Measurement Variables	412
6-2.1	Sampling	412
6-2.2	Sample Preparation	412
6-2.3	Field Selection	413
6-3	Standard Chart Methods	414
6-4	Measurement of Structural Gradients	414
6-4.1	Decarburization	415
6-4.2	Case Depth	417
6-4.3	Coating Thickness	422
6-5	Stereology Terminology	423
6-6	Volume Fraction	425
6-6.1	Areal Analysis	426
6-6.2	Lineal Analysis	426
6-6.3	Point Counting	426
6-6.4	Statistical Analysis	428
6-6.5	Comparison of Methods	432
6-6.6	Summary	435
6-7	Grain Size	435
6-7.1	Grain Shape	435
6-7.2	Grain Size Measurement	436
	<i>Delineation of Grain Boundaries / Standard Chart Methods / Jeffries Planimetric Method / Triple-Point Count Method / Heyn Intercept Method / Nonequiaxed Grains / Duplex Grain Structures / Two-Phase Structures / Snyder-Graff Intercept Method / Fracture Grain Size / Accuracy of Grain Size Estimates / Relationship of <math>\bar{L}_3</math> to Other Grain Parameters</i>	
6-7.3	Grain Size Distributions	465
6-7.4	Summary	471
6-8	Inclusion Rating Methods	472
6-8.1	Chart Comparison Methods	472
6-8.2	Nonchart Rating Methods	474
6-8.3	Inclusion Deformability	477
6-8.4	Summary	479
6-9	Line Length	480
6-10	Spacings	480
6-10.1	Mean Free Path and Mean Spacing	480
6-10.2	Interlamellar Spacing	481
6-11	Contiguity	485
6-12	Anisotropy	486
6-13	Shape	486
6-14	Particle Size	488

6-15	Electron Microscopy Techniques	493
6-16	Quantitative Fractography	494
6-17	Image Analysis	499
6-18	Applications	502
6-19	Summary	502
<b>Appendixes</b>		<b>509</b>
A	Etchants for Revealing Macrostructure	509
B	Macroetchants Based on Copper-Containing Compounds—For Etching of Iron and Steel	533
C	Macroetchants for Revealing Strain Patterns in Nonferrous Metals	536
D	Electroless and Electrolytic Plating Procedures	538
E	Electromechanical Polishing Procedures	541
F	Attack Polishing Procedures	543
G	Chemical Polishing Solutions	552
H	Electrolytic Polishing Solutions	562
I	Etchants for Revealing Microstructure	610
J	Dislocation Etching Techniques	712
<b>Indexes</b>		<b>733</b>
Author Index		
Subject Index		